Magnum Board 16mm Weatherboard Direct Fix


Sheet List		
Sheet Number	Sheet Name	Current Revision
000	Cover Sheet	
1/31	Concrete Foundation Detail	
2/31	Timber Foundation Detail	
3/31	External Corner Detail	
4/31	External Corner Detail	
5/31	Internal Corner Detail	
6/31	Internal Corner Detail	
7/31	Eave - Section Detail	
8/31	Barge - Section Detail	
9/31	Roof - Wall Ridge - Section Detail	
10/31	Canopy Junction - Section Detail	
11/31	Horizontal Control Joint	
12/31	Vertical Joint On Stud	
13/31	Typical Head and Sill Detail	
14/31	Typical Jamb Detail	
15/31	Deck Threshold Detail	
16/31	Pipe Penetration - Plan & Section Detail	
17/31	Concrete Foundation Detail	
18/31	Steel Floor Detail	
19/31	External Corner Detail	
20/31	External Corner Detail	
21/31	Interior Corner Detail	
22/31	Interior Corner Detail	
23/31	Eave - Section Detail	
24/31	Barge - Section Detail	
25/31	Roof - Wall Ridge - Section Detail	
26/31	Canopy Junction - Section Detail	
27/31	Horizontal Control Joint	
28/31	Vertical Control Joint Detail	
29/31	Typical Head and Sill Detail	
30/31	Typical Jamb Detail	
31/31	Pipe Penetration - Plan & Section Detail	



000

Health Based Building Magnum Board 16mm Weatherboard Direct Fix Cover Sheet








Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Concrete Foundation Detail



29/11/2019 5:26:23 PM

00




Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Timber Foundation Detail

29/11/2019 5:26:23 PM

100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

External Corner Detail



29/11/2019 5:26:23 PM

100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

External Corner Detail



29/11/2019 5:26:24 PM

100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Internal Corner Detail



29/11/2019 5:26:24 PM


100





Health Based Building Magnum Board 16mm Weatherboard Direct Fix Internal Corner Detail






29/11/2019 5:26:24 PM

100

20

Eave - Section Detail






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Barge - Section Detail



29/11/2019 5:26:24 PM





Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Roof - Wall Ridge - Section Detail



29/11/2019 5:26:24 PM

00

Canopy Junction - Section Detail




10/31

Health Based Building Magnum Board 16mm Weatherboard Direct Fix Canopy Junction - Section Detail



29/11/2019 5:26:24 PM






Health Based Building Magnum Board 16mm Weatherboard Direct Fix Horizontal Control Joint



100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix Vertical Joint On Stud




29/11/2019 5:26:25 PM



20




Typical Head Detail



Typical Sill Detail










100




10mm






Typical Jamb Detail

14/31









29/11/2019 5:26:25 PM

Health Based Building Magnum Board 16mm Weatherboard Direct Fix Deck Threshold Detail




100






Pipe Penetration Section Detail



16/31

Health Based Building Magnum Board 16mm Weatherboard Direct Fix Pipe Penetration - Plan & Section Detail








Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Concrete Foundation Detail



29/11/2019 5:26:26 PM

00




29/11/2019 5:26:26 PM

100

20

Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Steel Floor Detail






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

External Corner Detail



29/11/2019 5:26:26 PM

100




29/11/2019 5:26:26 PM

100

20

Health Based Building Magnum Board 16mm Weatherboard Direct Fix

External Corner Detail






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Interior Corner Detail



29/11/2019 5:26:26 PM

100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Interior Corner Detail



29/11/2019 5:26:26 PM






Health Based Building Magnum Board 16mm Weatherboard Direct Fix





29/11/2019 5:26:26 PM

100






Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Barge - Section Detail



29/11/2019 5:26:26 PM





Health Based Building Magnum Board 16mm Weatherboard Direct Fix


Roof - Wall Ridge - Section Detail



29/11/2019 5:26:27 PM

00







Canopy Junction - Section Detail (Steel)

26/31









Health Based Building Magnum Board 16mm Weatherboard Direct Fix

Vertical Control Joint Detail




29/11/2019 5:26:27 PM

100




20






29/31












Typical Jamb Detail (Steel)




Health Based Building Magnum Board 16mm Weatherboard Direct Fix Typical Jamb Detail





Pipe Penetration Section Detail (Steel)



Pipe Penetration Plan Detail (Steel)



31/31

Health Based Building Magnum Board 16mm Weatherboard Direct Fix Pipe Penetration - Plan & Section Detail

